

**Golden Spike Disposal Facility Analytical Testing Requirements  
Non-Oilfield Waste**

- Non-oilfield waste must be non-hazardous.
- The analytical testing below is the minimum required; additional testing may be needed for some waste streams.
- Please contact the Facility Administrator for more information: **587.414.5920**

Minimum Testing Requirements:

|                                |
|--------------------------------|
| <b>pH</b>                      |
| <b>Flashpoint (°C)</b>         |
| <b>Leachable BTEX (mg/L)</b>   |
| - Benzene                      |
| - Ethylbenzene                 |
| - Toluene                      |
| - Xylenes                      |
| <b>Leachable Metals (mg/L)</b> |

Analytical testing must be completed by an accredited laboratory. Please contact the laboratory to ensure you have the correct sample container for each test, and that you transport the samples appropriately.

Upon receipt of the analysis results, please complete a Waste Approval Application and submit it with a signed copy of the laboratory analysis results to the Facility Administrator.

**Hydro Vault cannot accept any waste until all documents have been received and an approval has been issued.**